

RUSS CONNORS ASSOCIATES

Consulting Structural Engineers

7801 Orangethorpe Avenue
BUENA PARK, CALIFORNIA 90620

Phone (213) 868-7764 (714) 522-2836

DATE 3-16-71	TIME 7:00 AM
PROJECT GLENDDORA LIBRARY	
LOCATION	
CONTRACTOR	OWNER
WEATHER	TEMP
PRESENT AT SITE CHRIS PRENTICE RUSS CONNORS	

TO
ANTHONY & LANGFORD
12422 E WHITTIER
WHITTIER, CAL 90602
ATTN: ROGER WILLNER

NO COMMENTS WERE NOTED.

SOUTH & WEST (LOWER-LEVEL) WALLS WERE BEING GROUTED. THE PIER ON LINE 4 DIDNT HAVE THE REQUIRED AMOUNT OF VERTICAL STEEL IN IT, BUT, FORTUNATELY, THE GROUT HAD NOT SET UP, AND THE BAR COULD BE SHOVED DOWN. HOWEVER, THE WALL WAS SEPARATED AT THE JAMB LINE. THIS IS NOT ACCORDING TO DETAIL (1/All). I SUGGEST AS A REMEDY, THAT A PIPE COLUMN BE PLACED IN THIS SEPARATION TO SUPPORT THE GIRDER ABOVE (IF THE LOCATION IS PROPER).

OUR PURPOSE OF THE VISIT WAS TO UNDERSTAND THE PROBLEMS OF THE LARGE POUR, AND ADAPT TO THE CONTRACTORS METHODS IF AND WHERE POSSIBLE.



COPIES TO _____

FIELD INSPECTION REPORT

SIGNED Bo HOFFMAN